

Gary J. Leikas  
7405 S.E. Tibbetts  
Portland, Oregon 97206  
U. S. A.

6th April 1977.

W. J. Walwyn  
Morgan Motor Co. Ltd.  
Pickersleigh Road.  
Malvern Link.  
Worcs. WR14 2LL.  
England.


Dear Mr. Walwyn,

Enclosed with this letter you will find a check for £ 68.21 to cover the balance due on my last order. I do wish to thank yourself and Mr. Baldwin for your help and understanding in completeing my own order and Julian Graham's order in such good time. And I also wish to thank you both for working with Mr. Bill Casey in shipping all of the parts and for saving us the trouble of the VAT. I am sure it is extremely difficult for you to do bussiness with people living such great distances away from England. Misunderstandings and questions cannot be easily cleared up. I hope you did not feel I was being a bit brash or over bearing in calling you up at the factory. My only thought was to secure a complete understanding between your end and the parties at this end. I hope to visit England next year and will surely visit the factory and pay my respects to both you and Mr. Baldwin.

Now then, down to parts and orders. Along with this letter you will find lists of various items members of our local club need for maintance or rebuilding of their Mogies. First on the list you will find Julian Graham. The first two items on his list will be the front disc brake rotors and the seat cushions c/w interiors that you were unable to ship with his last order. He will still need these items, so we will list them again on this order. Also next on his list you will see the disc brake calipers we thought we didn't need. We have found that the calipers we had will not work as anticipated. So we will include these on this order also. These will be the type calipers used on the current 4/4.

If you could please return to me a Pro Forma Invoice on these items listed for the various Morgans. Upon receipt of the invoice I will mail off to you a bank draft for the needed amount. The shipping will be, as before, through the good services of Bill Casey. And it is planned that all the various orders should be shipped together.

Sincerely yours,

A handwritten signature in cursive script that reads "Gary J. Leikas". The signature is written in dark ink and is positioned above the printed name.

Gary J. Leikas

President, Morgan Owner's Group, Northwest.

---

FOR: Morgan Owner's Group, Northwest  
care of Gary J. Leikas

Mr. Julian Graham - 1956 - 4/4 Two-seater RHD - Chassis Number A246

1. Pair (2) Disc Brake Rotors - As Used On Current 4/4.
1. " Seat Cushions c/w Interiors....(Black Leather)
1. " Disc Brake Calipers - As Used On Current 4/4.
1. Set (2) Side Valence - RH and LH.
1. Metal Box Grille Is Bolted to, Held In Place By RH and LH Side Valence.

Mr. Dan Warren - 1963 - 4/4 Two-seater RHD - Chassis Number ????

1. Set (2) Side Valence - RH and LH.
1. Metal Box Grille Is Bolted to, Held In Place By RH and LH Side Valence.
1. Wire Wheel Luggage Rack.

Mr. David Schwabe - 1961 - +4 Two-seater LHD - Chassis Number 4544

1. Pair Windscreen Wiper Arm.
1. Set Upper and Lower Bracket That Mount The Front Bumper Blade To The Frame Front.
1. Emergency Brake Cable.
1. Female Drive Gear For Speedo, As Fitted At Gear Box.
1. Set (4) Side Screen Clamps - Complete.
1. Strengthened Frame Front.
1. Pair Steering Dampers.
1. " Thrust Pads.
1. " King Pins.
1. " " " Bolts.
1. Set (4) King Pin Bushes.
1. Pair Fittings That Thread Into King Pin Bolts c/w collar that Seals Oil Line Into King Pin Bolt.
1. Set (2) Side Valence - RH and LH.
1. Front Oil Seal - Moss Gearbox.
1. Rear Oil Seal - Moss Gearbox.
1. Set Gearbox Gaskets
1. Thermostat Housing - As Used With Morgan Installation Of Triumph Engine.

OR: Morgan Owner's Group, Northwest  
care of Gary J. Leikas

Mr. Douglas Barofsky - 1962 - +4 Super Sports LHD - Chassis Number 4996

1. Pair Rebound Springs.
1. " Steering Dampers.
1. " Thrust Pads.
1. " King Pins.
1. " " " Bolts.
1. Set " " Bushes (4).
1. Pair Bonnet Buffer Rubbers - Rubbers only.
1. Windscreen Weather Rubber.
6. Dovetail Rubbers.
1. Pair Running Board Tred Rubbers.
1. " Aluminium Tread Plates.
20. Wing Rubbers.
1. Pair Radiator Mounting Rubbers.
1. " Windscreen Wiper Blades.
1. Mounting Bracket That Is Bolted To Scuttle - Holds Old Style Steering Column In Place As It Runs Through Scuttle.
2. Sets (4 pieces) Upper and Lower Bracket That Mount The Front Bumper Blade To The Front Frame.
1. Handbrake Cable c/w End Fittings.
1. Track Rod, 38½ inches long - Runs From Stub Axle TO Stub Axle.
1. Spare Wheel Clamp Screw c/w Hold Down Plate and Washer.
4. Door Hinges - Brass.
1. Wire Wheel Luggage Carrier.
1. Front Oil Seal - Moss Gearbox.
1. Rear Oil Seal - Moss Gearbox.
1. Set Gearbox Gaskets.
2. Clutch Carbon Block.
2. Front Differential Seal.
2. Sets Oil Seals - Rear Axle (4)

FOR: Morgan Owner's Group, Northwest

care of Gary J. Leikas

Mr. Mike Manning - 1965 - +4 Two-seater LHD - Chassis Number 5832

1. Windscreen c/w Laminated Glass, Mounting Bracket Rubber Pads, Weather Rubber, and All Mounting Brackets, As Would Be Used On A +4 Of This Vintage, With The Exception Of The Mounting Brackets That Mount Directly On To The Scuttle.
1. Pair Dovetail Rubbers.
1. " Anti Scuttle Rubbers.
1. Set (2) Side Valence - RH and LH.
1. " Wing Welting - Rubber Strip That Lies Between Wings and Body.
2. Sets (4 pieces) Upper and Lower Bracket That Mount The Front Bumper Blade To The Front Frame.
1. Metal Box Grille Is Bolted To, Held In Place By RH and LH Side Valence.
1. Hood Frame Complete (three pieces) - Type That Would Be Used On +4.
1. Pair Hood Frame Swivel Brackets c/w With Spacers.
1. 'Morgan' Script.
1. Angle Bracket Used To Mount Steering Box To Frame Front.
1. Aluminium Clamp That Is Affixed To Steering Column, This Clamp In Turn Is Bolted To Like Clamp That Is Affixed To Bar That Runs The Width Of Body Behind The Dash.
1. Mounting Bracket That Is Bolted To Scuttle, Holds The Old Style Steering Column In Place As It Runs Through The Scuttle.
1. Pair Aluminium Tread Plates.
1. " Running Board Tread Rubbers.
2. Yard Hydram Banding.
1. Strengthened Frame Front.
1. Pair King Pins.
1. " " " Bolts.
1. Set " " Bushes (4).
1. Pair Thrust Pads.
1. " Steering Dampers.
1. Set (4) Side Screen Clamps - Complete.

FOR: Morgan Owner's Group, Northwest  
care of Gary J. Leikas

Mr. Jerry Stubblefield - 1962 - +4 Four-seater RHD - Chassis Number 4975

1. Set (2) Side Valence - RH and LH.
1. Pair Door Latches - Latest Type.
1. " Bonnet Buffer Rubber - Rubber only.
2. Yards Hydram Banding.
1. Pair Aluminium Tred Plate.
1. Windscreen Weather Rubber.
1. Pair King Pin Bolts.
1. " Fittings That Thread Into King Pin Bolt c/w Collar That Seals Oil Line Into King Pin Bolt.
1. " Thrust Pads.
1. " Steering Dampers.
1. Mounting Bracket That Is Bolted to Scuttle - Holds Old Style Steering Column In Place As It Runs Through Scuttle.
8. Side Screen Clamps - Complete.
1. Rear Number Plate Panel - As Used On This Style Morgan.

Mr. David Sweeney - 1959 - +4 Four-seater LHD - Chassis Number 4153

2. Windscreen Wipers.
4. Door Hinges - Brass.
1. Pair Steering Dampers.
1. " Thrust Pads.
1. " King Pins.
1. " " " Bushings.
1. " " " Bolts.
1. Windscreen Weather Rubber.
1. Windscreen Mounting Bracket Rubber Pads - Old Style.
1. Tachometer Cable.
1. Speedo Cable.
11. Feet Bonnet Tape.
2. Rubber Pedal Cover - For Clutch and Brake Pedals.

FOR: Morgan Owner's Group, Northwest  
care of Gary J. Leikas

Mr. Jay Brandon - 1967 - +4 Two-seater RHD - Chassis No. 6574

1. Pair Steering Dampers.
1. " Dovetail Rubbers.
1. " Running Board Tred Rubbers.
1. " Windscreen Wiper Blades.
1. " Rubber.
1. " Mounting Bracket Rubber.
1. Set (2) Mounting Brackets That Hold Windscreen On To The Scuttle Brackets.
11. Feet Bonnet Tape.
1. Set Wing Welting - Rubber Strip That Lies Between Wings and Body.
1. Pair Anti Scuttle Rubbers.
1. " Aluminium Tred Plates.
1. 'Morgan' Script.
1. Bracket That The Rear Number Plate Lamp Is Bolted To.

Mr. Ron Joy - 1961 - +4 Two-seater LHD - Chassis Number ????

1. Pair Steering Dampers.
1. " Thrust Pads.
1. " King Pins.
1. " " " Bolts.
1. Set " " Bushes (4).
1. Thermostat Housing - As Used With Morgan Instalation of Triumph Engine.

Mr. Bob Hauge - 1962 - 4/4 Two-seater LHD - Chassis Number A625

1. Wire Wheel Luggage Carrier.

Mr. Gary J. Leikas - 1970 - +8 Two-seater RHD - Chassis Number R7172

1. Wire Wheel Luggage Carrier.
1. Spare Wheel Clamp Screw c/w Hold Down Plate and Washer.

Mr. Davy Crocket - 1966 - 4/4 Two-seater LHD - Chassis Number B1252

1. Wire Wheel Luggage Carrier.